

Lagondaforum: 1930 2 litre starter motor failure

1930 2 litre starter motor failure

Written by john@oakeswood.com at Apr 24, 2020 11:45 am

I have a 1930 2 litre supercharged Lagonda. This underwent a full engine re-build last year. The starter motor has failed in that although it turns - a whirring sound can be heard - it is clearly not now engaging with the engine.

Does anyone have experience of this problem and what may be required to resolve it - and how? i can forward a short video by WhatsApp if that would help.

Thank you

John
07860 490604

Re: 1930 2 litre starter motor failure

Written by Peter S30 at Apr 24, 2020 12:20 pm

Dear John

To access the starter motor assembly, best is to remove the front seats and the floorboard. But for a quick look you also can creep under the car, left side, and have a look. The starter motor has a sort of Hardy disc coupling between the motor and the drive, which can disengage. I also once had a spline that fell out, I could fix this "en route". And there is a spring that can break (recommended standard spear part), see club spares.

I have attached scans from the Vintage Lagonda Handbook and the 2 Litre Low Chassis Type Instruction Book. Both highly recommended and can be supplied by the Club

Attachments:

[2ltr LC Lagonda_pg12.png](#) (filesize: 146.66 KB)

[Bendix vintage Lagonda 1.png](#) (filesize: 80.79 KB)

[Bendix vintage Lagonda 2.png](#) (filesize: 95.88 KB)
